Release Note for Vigor2926 Series

Firmware Version:	3.8.9.2
Release Type:	Normal
Applied Models:	Vigor2926, Vigor2926n, Vigor2926ac, Vigor2926L, Vigor2926Vac, Vigor2926Ln, Vigor2926Lac

Vigor2926 series is a broadband router which integrates IP layer QoS, NAT session/bandwidth management to help users control works well with large bandwidth. The state-of-art routing feature, VPN security, and Dual-WAN provide integrated benefits for professional users and small offices.

New Features

- None.

Improvement

- Improved: Enhanced the security on the web server.
- Corrected: Firewall did not work on routed LAN.
- Corrected: Unable to keep network connection via built-in LTE modem.
- Corrected: Available wireless LAN 5G channels for some countries were not correct.
- Corrected: NAT loopback did not work when port setting was configured with a number from 768 to 1023.
- Corrected: The word, DMZ, disappeared on the Dashboard after enabling the DMZ port (LAN>>General Setup) and refreshing the web page of Dashboard.
- Corrected: The wireless device was able to connect to WLAN (2.4G). After disconnecting WLAN (2.4G), the device was unable to reconnect to WLAN (5G) and received error message of wrong security key.
- Corrected: Unable to reboot Vigor router for the built-in LTE modem was in the reset state.

Known Issue

- None.

RD NO: 107_07_17